


svářečka RTB
ZAPOJENÍ SVOREK NA PŘEPÍNAČI



ze zapojení vytáhl bobobo
SYSTÉM SEPNUTÍ V KONTAKTECH

	70	60	50	VYP	65	85	105	125	150
1-2		X	X						
3-4	X		X						
5-6	X	X							
N 7-8	X	X	X						
L ₂ 9-10	X	X	X						
L ₁ 11-12					X	X	X	X	X
L ₂ 13-14					X	X	X	X	X
15-16					X				
17-18						X			
19-20							X		
21-22								X	
23-24									X

svorka 7 N **svorka 11 L₁** **svorky 10,14 L₂**
 svorky 7-11 230 svorky 14-11 400