

## CHASSIS-VERGLEICH

| <b>THOMSON-CHASSISVERGLEICH</b> |                   |                     |                  |
|---------------------------------|-------------------|---------------------|------------------|
| <b>THOMSON</b>                  | <b>TELEFUNKEN</b> | <b>SABA</b>         | <b>NORDMENDE</b> |
| ICC4                            | 417               | SC90                | F14              |
| ICC5                            | 517-518-617-618AB | SX50-SX55-SX58      | F15-F16-F17-F18  |
| ICC6                            | ICC6              | ICC6                | ICC6             |
| ICC7-ICC8                       | 418B-418C         | SB70-SB75-SC80-SC85 | F23-F24          |
| ICC9                            | ICC9              | ICC9                | ICC9             |
| ICC10-ICC11                     | ICC10-ICC11       | ----                | ICC10-ICC11      |
| IDC2                            | 619-619A          | SB220               | DC1-DC2          |
| IKC2                            | 418A-418A1        | SX20-SX25           | F19-F20          |
| TX80                            | 318A              | SX08                | F22              |
| TX805                           | TX805             | TX805               | TX805            |
| TX90                            | 318B              | SC09                | F26              |
| TX91                            | TX91              | TX91                | TX91             |
| TX92-TX92F                      | TX92-TX92F        | TX92-TX92F          | TX92-TX92F       |
|                                 |                   |                     |                  |
|                                 |                   |                     |                  |